



जवाहरलाल नेहरु पत्तन प्राधिकरण JAWAHARLAL NEHRU PORT AUTHORITY

ISO 9001 : 2011
ISO 14001 : 2011
ISO 27001 : 2011
ISO 45001 : 2011

पत्तन कार्यालय : प्रशासन भवन, शेवा, नवी मुंबई - 400707. Port Office : Administration Bldg., Sheva Navi Mumbai - 400 707.
मुख्य सतर्कता अधिकारी Chief Vigilance Officer - (022) 2724 4151 : मुख्य प्रबंधक (प्रशासन) एवं सचिव Chief Manager (Admn.) & Secy - (022) 2724 4021 :
मुख्य प्रबंधक (यातायात) Chief Manager (Traffic) - (022) 2724 4191 : मुख्य प्रबंधक (यां.पं.वि.अ.) Chief Manager (M&EE) - (022) 2724 4181 :
मुख्य प्रबंधक (वित्त) Chief Manager (Fin) - (022) 2724 4081 : मुख्य प्रबंधक (प.यो.वि.) Chief Manager (PP&D) - (022) 2724 4156
उप-संरक्षक Dy. Conservator (022) 2724 4171 : हार्बर मास्टर (022) 2724 4173.
Website : www.jnport.gov.in • Email : info@jnport.gov.in

JNP/Marine/DC/Cir./2024/


Date: 21/05/2024.

CIRCULAR

Sub: Monsoon preparedness (from 1st June to 30th Sept'2024).

All concerned are hereby informed to take note the following and take necessary action.

1. The Area Cyclone Warning Centre, India Meteorological Department, Mumbai replays the port warning message whenever occasion demands. The Weather Section (WS) is manned 24 hrs and is contactable on Telephone No. 2215 0431 & Fax No. 2216 0824.
2. All vessels in port shall keep their Main Engines standby on short notice. Masters of vessels shall ensure additional mooring ropes are made fast whenever occasion demands. Also, it will be ensured that there are sufficient crew on board to tackle any emergencies. It may be noted that no immobilization of Main Engines is allowed. Vessels will keep continuous watch on VHF Channel 13 in case of emergency.
3. The launch service provided by JNPA running between Mumbai and JNP may be suspended without notice whenever occasion demands.
4. All emergencies shall be dealt with, as details in the Port's Emergency Action Plan. JN Port Control's Telephone Nos. are 022-2724-5178, 022-2724-5151, 022-6781-5178,, Mobile NO. 9769508085 and is manned round the clock with continuous watch on VHF Channel 13 in case of emergency.
5. Duty Dock Master Mobile No. 8291989743.
6. During foul weather, CB, LB2, BMCT 1 and SB vessel to be berthed heading south.
7. No cold move permitted in JNPA water except in emergency with approval of Harbour Master/Deputy Conservator.


(Capt. Balasaneb Pawar) 21/05/2024
Deputy Conservator

To,

1. Ship Owners/Masters/Agents
2. MANSA/CSLA/INSA
3. DP World/BPCL/APMT/BMCTPL

Copy to :

1. All HODs.
2. DM-I/DM-II
3. Managers(MCB/LCB & SWB-I/II/ICD & SB-III)
4. Port Control
5. Rajbhasha Adhikari
6. PS to Chairman/Dy. Chairman



जनेप प्राधिकरण
JNPA

जवाहरलाल नेहरु पत्तन प्राधिकरण JAWAHARLAL NEHRU PORT AUTHORITY

ISO 9001 : 2015
ISO 14001 : 2015
ISO 27001 : 2013
ISO 45001 : 2018

पत्तन कार्यालय : प्रशासन भवन, शेवा, नवी मुंबई - 400707. Port Office : Administration Bldg., Sheva Navi Mumbai - 400 707.
मुख्य सतर्कता अधिकारी Chief Vigilance Officer - (022) 2724 4151 : मुख्य प्रबंधक (प्रशासन) एवं सचिव Chief Manager (Admn.) & Secy - (022) 2724 4021 :
मुख्य प्रबंधक (यातायात) Chief Manager (Traffic) - (022) 2724 4191 : मुख्य प्रबंधक (मॉ.एव.वि.अ.) Chief Manager (M&EE) - (022) 2724 4181 :
मुख्य प्रबंधक (वित्त) Chief Manager (Fin) - (022) 2724 4081 : मुख्य प्रबंधक (प.यो.वि.) Chief Manager (PP&D) - (022) 2724 4156
उप-संरक्षक Dy. Conservator (022) 2724 4171 : हार्बर मास्टर (022) 2724 4173.
Website : www.jnport.gov.in • Email : info@jnport.gov.in

JNP/Marine/HM/Cir/2024/33g

04.06.2024.

CIRCULAR


Sub: Alternate Means of Pilot transfer arrangement for vessels having less than 3 mtrs freeboard at pilot door during monsoon (1st June -30th Spt.)

Some container visiting JNPA has pilot door arrangement as main means for pilot transfer. This vessel when loaded with deeper drafts leads to a freeboard less than 3 mtrs at pilot transfer area (Pilot Door). During monsoon season prevailing sea swell in pilot boarding area makes this pilot transfer arrangement completely impractical, unworkable and highly unsafe for pilot transfer. Such arrangement has cause near misses in port while pilot transfer at pilot station.

All stakeholders are informed that vessels with pilot door arrangement must have alternate means of pilot transfer which can be combination ladder arrangement in accordance with SOLAS Regulation V/23 & IMO resolution A.1045(27).

All Vessels with Combination ladder, Accommodation ladder's Lower Horizontal platform should be more than 5 mtrs above sea-level.

All vessels arriving JNPA to comply above to avoid non availability of Pilotage Service due to safety concern.


(Capt. Shashikant Jadhav)
Harbour Master

To:

1. Ship Owners/Masters/Agents
2. MANSA/CSLA/INSA
3. DpP World/BPCL/APMT/BMCTPL

Copy to :

1. All HODs.
2. DM-I/DM-II
3. Managers(MCB/LCB & SWB-I/II/ICD & SB-III)
4. Port Control
5. Rajbhasha Adhikari
6. PS to Chairman/Dy.Chairman